

Corporate Hazard Identification & Risk Control

HIRA # 15.68

Torch Cutting and Welding

Applicable Zones:	Project Yard Office	Asphalt Plant			
HAZARD(S)					
 Fire Risk (P) Use of Propane (H) Risk of Property Damage (P) Gas Leak (H) 					
PRE-CONTROL RISK					

PRE-CONTROL RISK					
Likelihood		Consequence	Pre-Control Risk		
3		5	15		
CONTROLS					
Elimination	Hire a contractor to complete work that you cannot complete safely.				
Substitution	Ensure that the cost and risk of the task isn't offset by the cost of purchasing new.				
Engineering	All torches, welders, tanks, hoses must be inspected and checked for leaks before use.				
Administrativ e	Hot Work Permit required for the task.				
PPE	High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be always worn.				

POST CONTROL RISK					
Likelihood	Consequence	Post-Control Risk	Risk Reduction	Critical or Not Critical	
1	5	5	10	No	

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES	
WHMIS Legislation	J-AAR Manual: P1.3.14	
O.Reg 213/91: S. 42-43	J-AAR Manual: P1.4.8	
O.Reg 854: S. 30	J-AAR Manual: P1.4.19	