	Corporate Hazard Identification & Risk Control HIRA # 15.16								
Applicable Z	ones:	Project	Ya Ya	ird		Office	Asphalt F	Plant	
HAZARD(S) Musculoskeletal Disorders (P) Slip, Trip and Fall in slippery surfaces due to water (P) Exposure to Exhaust fumes due to work being completed (H) 									
Likelihood 2			PRE-CONTROL RISK Consequence 4			Pre-Control Risk 8			
CONTROLS									
EliminationUse nearby equipment to lift pumps if needed, avoiding Musculoskeletal issue.SubstitutionEnsure the pump is located correctly. Ensure exhaust is not able to accumulate in a trench or					or				
Administrative	Engineering excavation. Iministrative Consult J-AAR's procedure for safe lifting practices.								

PPE High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times.

		POST CONTROL RISK		
Likelihood	Consequence	Post-Control Risk	Risk Reduction	Critical or Not Critical
1	4	4	4	No

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES
 O.Reg 213/91: S315 O.Reg 213/91: S385 	J-AAR Manual P1.4.4 P1.4.5