



Corporate Hazard Identification & Risk Control

HIRA #
15.21

Extracting Stuck Equipment

Applicable Zones:	Project	X	Yard		Office		Asphalt Plant	
--------------------------	---------	--------------	------	--	--------	--	---------------	--

HAZARD(S)

- Struck by Potential (P)
- Pinch Point – Caught Between or Under (P)
- Property Damage (P)
- Eye Injury from Debris (P)

PRE-CONTROL RISK

Likelihood 2	Consequence 5	Pre-Control Risk 10
-----------------	------------------	--------------------------------

CONTROLS

Elimination	Inspect all towing devices/equipment before attempting to move the stuck piece of equipment.
Substitution	If the vehicle can not be moved safely, call towing company to manage the task.
Engineering	
Administrative	Ensure work area is clear of workers not involved in the task.
	Only operate equipment you are authorized to.
PPE	High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times.

POST CONTROL RISK

Likelihood 1	Consequence 5	Post-Control Risk 5	Risk Reduction 5	Critical or Not Critical No
-----------------	------------------	--------------------------------	---------------------	--------------------------------

LEGISLATIVE REFERENCES

- O.Reg 213/91: S14 (3-4)
- O.Reg 213/91: S21-27
- O.Reg 213/91: S93-116, S100
- O.Reg 213/91: S140

OTHER STANDARDS & REFERENCES

J-AAR Manual
P1.4.18 P1.5.4.18
P2.11.8 P2.12.11.8
P2.11.9 P2.12.11.9