	Corp	oorate Hazard Ider & Risk Contro Hand and Power To	וכ	HIRA # 15.29	
Applicable Z	ones: Projec t	Yard Vard Offi	ce Asp	ohalt Plant	
HAZARD(S)					
<ul> <li>Electric Shock (P)</li> <li>Eye Injury from Debris (P)</li> <li>Potential Noise over 85dbs (H)</li> <li>Laceration (P)</li> <li>Pinch Points (P)</li> <li>Punctures (P)</li> </ul>					
Likelihood 3		PRE-CONTROL RISK Consequence 4		ntrol Risk 12	
CONTROLS					
EliminationSubstitutionEngineeringAll power tools to be inspected before use. Defective tools are to be tagged and placed out of service.Administrativ e PPEPPEHigh Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times, additional PPE may be required.					
POST CONTROL RISK					

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES
O.Reg 213/91: S.21 O.Reg 213/91: S.93 O.Reg 213/91: S.195	J-AAR Manual: P1.4.7 J-AAR Manual: P1.5.4.7