	Corp	orate Hazard Ide & Risk Contr Heavy Lifting				
Applicable Z	Cones: Projec	Yard Of	fice Asphalt Plant			
HAZARD(S)						
 Musculoskeletal Disorders (P) Slip, Trip & Fall (P) Over Exertion (H) 						
PRE-CONTROL RISK						
Likelihood 3		Consequence 3	Pre-Control Risk 9			
CONTROLS						
Elimination	Do not carry anything so large that you cannot see where you are walking					
Substitution Engineering	Use equipment to move material when feasible. Ask for assistance when moving heavy material.					
Administrativ	Follow J-AARs SJP for safe lifting techniques.					
e PPE	High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times.					
POST CONTROL RISK						

Likelihood	Consequence	Post-Control Risk	Risk Reduction	Critical or Not Critical	
1	3	3	6	No	

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES	
O.Reg 213/91: S. 384	J-AAR Manual: P1.4.17	
O.Reg 854: S.254	J-AAR Manual: P1.5.4.17.1	