



# Corporate Hazard Identification & Risk Control

HIRA #  
15.40

## Lack of Inspection

<b>Applicable Zones:</b>	Project	<input checked="" type="checkbox"/>	Yard	<input checked="" type="checkbox"/>	Office	<input checked="" type="checkbox"/>	Asphalt Plant	<input checked="" type="checkbox"/>
--------------------------	---------	-------------------------------------	------	-------------------------------------	--------	-------------------------------------	---------------	-------------------------------------

### HAZARD(S)

- Equipment Failure (P)
- Breakdown (P)
- Injury from Mechanical Failure (P)

### PRE-CONTROL RISK

Likelihood 3	Consequence 5	<b>Pre-Control Risk 15</b>
-----------------	------------------	--------------------------------

### CONTROLS

**Elimination**  
**Substitution**  
**Engineering**  
**Administrative**

Inspections are required to be completed daily on all equipment, or prior to each use.

High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times.

**PPE**

Needs to be inspected before each use.

### POST CONTROL RISK

Likelihood 1	Consequence 5	<b>Post-Control Risk 5</b>	Risk Reduction 10	Critical or Not Critical No
-----------------	------------------	--------------------------------	----------------------	--------------------------------

#### LEGISLATIVE REFERENCES

Awareness & Training  
O.Reg 297/13  
Mines and Mining Plants  
O.Reg 854  
Construction Regulations  
O.Reg 213/91  
Confined Spaces  
O.Reg 632/05

#### OTHER STANDARDS & REFERENCES

J-AAR Manual: P1.2.6  
J-AAR Manual: P1.4.14  
J-AAR Manual: P2.10.2  
J-AAR Manual: P2.13.2