

## Corporate Hazard Identification & Risk Control

HIRA # 15.77

## Working On or Near Water

Applicable Z	ones:	Project	Ya	ırd		Office		Asphalt Plant	
HAZARD(S)									
<ul><li>Drowning (P)</li><li>Hypothermia (P)</li></ul>									
PRE-CONTROL RISK									
Likelihood 3			Consequence 5				Pre-Control Risk 15		
CONTROLS									
Elimination Substitution	Water can be diverted or dammed in order to provide a dry working area, if feasible.								
Engineering Administrative	Guardrails or travel restraints must be used to restrict worker's risk of falling into water. If there is a drowning risk, then no worker shall work alone.								

POST CONTROL RISK							
Likelihood	Consequence	Post-Control Risk	Risk Reduction	Critical or Not Critical			
1	5	5	10	No			

**PPE** High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be always worn.

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES		
O.Reg. 213/91: S. 26-27	J-AAR Manual: P1.4.20		