



# Corporate Hazard Identification & Risk Control

HIRA #  
15.78

## Working Outside on High UV Days

<b>Applicable Zones:</b>	Project	<del>X</del>	Yard		Office		Asphalt Plant	
--------------------------	---------	--------------	------	--	--------	--	---------------	--

### HAZARD(S)

- Radiant Exposure (P)
- Burns (P)
- Occupational Illness (H)

### PRE-CONTROL RISK

Likelihood 4	Consequence 3	<b>Pre-Control Risk 12</b>
-----------------	------------------	--------------------------------

### CONTROLS

<b>Elimination</b>	Monitor weather conditions and shut down worksites if need be, for safety of workers.
<b>Substitution</b>	
<b>Engineering</b>	
<b>Administrative</b>	Consult the Ministry of Environments guides for skin protection
<b>PPE</b>	High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be always worn.

### POST CONTROL RISK

Likelihood 1	Consequence 3	<b>Post-Control Risk 3</b>	Risk Reduction 9	Critical or Not Critical No
-----------------	------------------	--------------------------------	---------------------	-----------------------------------

### LEGISLATIVE REFERENCES

OSHA: S.25(2)(h)

### OTHER STANDARDS & REFERENCES

J-AAR Manual: P1.4.17  
J-AAR Manual: P1.5.4.17.1  
J-AAR Manual: P1.5.4.17.2