

Corporate Hazard Identification & Risk Control

HIRA # 15.34

Housekeeping

Applicable Zones: Projec t Yard Office Asphalt Plant

HAZARD(S)

- Lacerations (P)
- Musculoskeletal Disorders (P)
- Slip, Trip and Fall (P)
- Puncture Injuries (P)
- Dust (H)

PRE-CONTROL RISK				
Likelihood	Consequence	Pre-Control Risk		

CONTROLS Elimination Substitution Engineering Administrativ PPE CONTROLS Look for housekeeping issues and clean them up. Maintaining the work as opposed to getting behind makes all the difference. Waste Material and debris shall be moved to a disposal area as often as is necessary to prevent a hazard. High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times.

POST CONTROL RISK					
Likelihood	Consequence	Post-Control Risk	Risk Reduction	Critical or Not Critical	
1	5	5	5	No	

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES
O.Reg 213/91: S. 35-48	J-AAR Manual: P1.4.10