

Corporate Hazard Identification & Risk Control

HIRA # 15.42

Laying Road Plates

Applicable Zones:	Projec t	\times	Yard		Office		Asphalt Plant	
-------------------	-------------	----------	------	--	--------	--	---------------	--

HAZARD(S)

- Slip, Trip and Fall (P)
- Musculoskeletal Disorders (P)
- Heavy Lifting (P)
- Pinch Points (P)

PRE-CONTROL RISK				
Likelihood	Consequence	Pre-Control Risk		
2	4	8		

CONTROLS

Elimination Use equipment near by if available

Substitution Engineering

Administrativ

Consult J-AAR Safe Work Procedure for Safe Lifting Practices

PPE High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times.

POST CONTROL RISK					
Likelihood	Consequence	Post-Control Risk	Risk Reduction	Critical or Not Critical	
1	4	4	4	No	

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES
	J-AAR Manual: P1.4.5