



Corporate Hazard Identification & Risk Control

HIRA #
15.46

Lock Out, Tag Out and Try Out

Applicable Zones:	Project	X	Yard	X	Office	X	Asphalt Plant	X
--------------------------	---------	---	------	---	--------	---	---------------	---

HAZARD(S)

- Lacerations (P)
- Musculoskeletal Disorders (P)
- Crushing Injuries (P)
- Puncture Injuries (P)
- Electrical Hazards (P)

PRE-CONTROL RISK

Likelihood 3	Consequence 5	Pre-Control Risk 15
-----------------	------------------	--------------------------------

CONTROLS

Elimination	LOTOTO Is used to de-energize equipment and prevent unwanted or accidental starting LOTOTO is required when a piece of equipment has been found unsafe to use due to defect or hazard.
Substitution	
Engineering	If a guard is to be removed, LOTOTO is required.
Administrative	Never being work on equipment without following J-AARs LOTOTO Policy and Procedure
PPE	High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be worn at all times.

POST CONTROL RISK

Likelihood 2	Consequence 5	Post-Control Risk 10	Risk Reduction 5	Critical or Not Critical Yes
-----------------	------------------	---------------------------------	---------------------	---------------------------------

LEGISLATIVE REFERENCES

O.Reg. 213/91: S. 190-191

OTHER STANDARDS & REFERENCES

J-AAR Manual: P1.4.12
J-AAR Manual: P1.5.4.12