

## Corporate Hazard Identification & Risk Control

HIRA # 15.72

## **Underground Hazards**

Applicable Zones:	Project	ard	Office	Asphalt Plant
	• C • In	AZARD(S) ollapse (P) jury (P) ury (P)		

PRE-CONTROL RISK				
Likelihood	Consequence	Pre-Control Risk		
4	5	20		

CONTROLS				
Elimination	No machine digging within 1m of utilities. Must be hand dug to daylight utilities.			
Substitution				
Engineering	Support all utilities in trench with proper procedures. Consult utility owner if necessary.			
Administrativ	Ensure J-AAR crews are in possession of valid locates before work commences.			
е				
PPE	High Visibility Clothing, Hard Hat & Safety Boots at a minimum must be always worn.			

POST CONTROL RISK				
Likelihood	Consequence	Post-Control Risk	Risk Reduction	Critical or Not Critical
2	5	10	10	Yes

LEGISLATIVE REFERENCES	OTHER STANDARDS & REFERENCES	
O.Reg 213/91: S104	J-AAR Manual	
Ŭ	P2.11.5	
O.Reg 213/91: S106	P2.11.10	
O.Reg 213/91: 228	P2.12.11.4	
O.Reg 362/05: S.20	P2.12.11.5	
5.1 (3g 302/00. 5.20	P2.12.11.10	